

UPDATE: A faulty dryer in the basement caused a fire late last night, triggering the sprinkler system. Water damage cleanup, re-establishment of the sprinkler system, and inspections by the fire and building departments must be completed before the Temple can reopen to the public.

Work is in progress, but we are unable to provide a timeline at this time. Please continue to check the website for future updates.